



**Photograph B-29. Carpy Connolly from Emmolo**



**Photograph B-30. Carpy Connolly from Emmolo**





**Photograph B-31. Carpy Connoly from northern Emmolo property**



**Photograph B-32. Carpy Connoly from northern Emmolo property**





**Photograph B-33. Local bank top erosion on Carpy Connolly property**



**Photograph B-34. Entrenched stage 4 channel from levee on northern Emmolo property**